


WEED LINE LAYDOWN (6 lbs.)

One 20" trunk, nine 23" limbs, one 33" cable, one quick link



1. Position trunk upright where slits appear as "V" shapes.
2. Insert one limb into outer V-shape and **angle tip down slightly** as you insert into V-shape directly across trunk.
3. Ensure limb is fit securely through V-shapes on both sides of trunk. MossBack products allow you to create multiple limb configurations (see below). Leave at least 4" of limb through one side of trunk.
4. Continue inserting limbs in trunk repeating first three steps.
5. Lay habitat on its side and loop cable through square openings in the trunk. Feed cable through brick and clip quick link to fasten ends of cable together.



Regular



All limbs to one side
(creates a stakebed)