


TROPHY TREE XL (16 lbs.)


One 60" Trophy Tree XL trunk, twelve 60" limbs

1. Position trunk upright where slits appear as "V" shapes.
2. Insert one limb into outer V-shape and **angle tip down slightly** as you insert into V-shape directly across trunk.
3. Ensure limb is fit securely through V-shapes on both sides of trunk. MossBack products allow you to create multiple limb configurations. Leave at least 4" of limb through on one side of trunk. See ideas below.
4. Continue inserting limbs in trunk repeating first three steps.

Weighting: A block adapter (for vertical placement) or laydown cable kit (for horizontal placement—see page 13) to attach a concrete block is recommended for secure placement and is sold separately. Concrete block is not included.



Regular



Widespread for maximum coverage



Regular



All limbs to one side (creates a stakebed)